

INSPECTION SHEET 検品書

OTHER その他

INSPECTION DATE		2025/10/29		CATEGORY		自走式木材破砕機 MOBILE WOOD CRUSHER				
MAKE	KOMATSU					MODEL	BR200T-1			
SERIAL	1212					STAMP	NOT FOUND			
HR METER	UNKNOWN		HR	Odometer	km			YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE				SHOE	500G		TIRE		

ENGINE	MODEL			S/N		
Oil leakage	FAIR	Attn		Oil	FAIR	Attn
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	FAIR	Attn
Sound	FAIR	Attn		EPA	YES · NO	

CONDITION	FAIR · Attn	
-----------	-------------	--

上物動作不良 OPERATIONS OF IMPLEMENTS: MALFUNCTION

コンベアひび割れあり、アクセルダイヤルでE/Gコントロール不可 CONVEYOR: CRACKED, UNABLE TO CONTROL THE ENGINE SPEED BY ACCELERATOR KNOB

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
--	---	-----------	---------------------------

COMMENT

HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION

下周りホース油漏れ小 SOME HOSE AROUND BOTTOM: OIL LEAKING

下周りコンベア近く油漏れ小 BOTTOM AROUND CONVEYOR: OIL LEAKING

ラジエータ周り油汚れあり AROUND RADIATOR: OIL STAINS

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	
--	---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。