

INSPECTION SHEET 検品書

GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2025/10/8	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	DENYO		MODEL	DCA-90SPH	
SERIAL	3611504		STAMP	NOT FOUND	
HR METER	8738	HR	TIRE SIZE		YEAR
					YR

ENGINE :		MODEL	S/N					
Oil leakage	FAIR	Attn	下部にじみあり BOTTOM: OIL OOZING	Oil	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE	MIDDLE	SEVERE	Exhaust Color	FAIR	Attn
Sound	FAIR	Attn		Radiator	FAIR	Attn		

GENERATOR				
RATED POWER	75 / 90	KVA	Leaking Breaker Condition	FAIR ▪ Attn
RATED AMPERE	217 / 236	A	Insulation Condition	FAIR ▪ Attn
Output Terminal	FAIR ▪ Attn			

COMPRESSOR				
RATED PRESSURE	Mpa Kgf/cm2		Unload Condition	FAIR ▪ Attn
RATED AIR FLOW	m3/min		Receiver Tank Condition	FAIR ▪ Attn
Compressor Oil Leak	FAIR ▪ Attn		Safety Valve Condition	FAIR ▪ Attn

CONDITION	FAIR ▪ Attn	

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
---	----------	------------------	----------------------------------

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。