

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/16	MAKE	HITACHI	MODEL	ZX200LC-3
SERIAL	HCM1U100C00202777		STAMP	HCM1U100C00202777	
HR METER	15865	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE :	MODEL	4HK1	S/N	408865
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn	にじみあり OIL OOZING		
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn	ガタあり SWING: LOOSE		
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn	ガタ、破れあり LOOSE, MUCH TORN		
Glasses	FAIR · Attn	F下部欠 LOWER WINDSHIELD: MISSING		
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn	右側油漏れ小 RIGHT CYLINDER: OIL LEAKING		
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
ATTACHMENT	FAIR · Attn	ガタあり LOOSE		
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
右Fキャリアローラー摩耗大 FRONT RIGHT CARRIER ROLLER: MUCH WORN		
ピンブッシュ割れあり SOME PIN BUSHES: CRACKED		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG ▪ WRIST	
Multi	MULTI ▪ 2 ▪ NO	
ARM-CRANE	YES ▪ NO	
BLADE	YES ▪ NO	
OFFSET	YES ▪ NO	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	YES ▪ NO	Breaker only ▪ Multi
COMMENT		
旋回モーター油漏れ小 SWING MOTOR: OIL LEAKING		
オイルフィルターにじみあり OIL FILTER: OIL OOZING		
コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING		
チャージ警告表示あり WARNING DISPLAY FOR CHARGING		
A/Cベルト欠 A/C: NO BELT		
モニター一部表示不良 MONITOR: PARTLY NOT DISPLAYING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。