

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/10/15	MAKE	KOMATSU	MODEL	D37PX-23	
SERIAL	80429			STAMP	KMT0D121TFA080429	
HR METER	2311	HR	SHOE	600LGP	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL 4D95LE-6 S/N 707005					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES · (NO)				
OPERATION PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	(PS) · DD	DIFF. STEERING	YES · (NO)		
Transmission	(FAIR)	Attn			
Travel	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · (FAIR) · DIRTY				
Operator's Seat	(FAIR)	Attn			
Glasses	(FAIR)	Attn			
AirCon	(A/C) · H/C · H only · C only · None				
BLADE & CYLINDERS					
BLADE	(FAIR)	Attn			
CYLD.(R)	(FAIR)	Attn			
CYLD.(L)	(FAIR)	Attn			
TILT CYLD	(FAIR)	Attn			
ANGLE CYLD	(FAIR)	Attn			

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT 			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
COMMENT 			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。