

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/9	MAKE	KATO	MODEL	KR-25H-V5
SERIAL No.	PLATE : 5410194		STAMP : KR258-0194		
HR METER	34703	HR	Odometer	3615	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · ☒ A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
TRANSMISSION		
Transmission	☒ FAIR · ☒ Attn	*1
No. OF GEARS	4	GEARS
4WD	☒ 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · ☒ Attn	破れあり CUTS
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
COMMENT		

BOOM				
No. of Section	4	SECTIONS		
CRACK/ENFORCEMENT	☒ FAIR · Attn			
DERRICKING CYL.	☒ FAIR · Attn			
EXTENSION CYL.	☒ FAIR · Attn			
JIB	☒ YES · NO			
JIB TYPE	STD · ☒ PWR			
MAIN & SUB WIRE	☒ YES · NO			
FREE FALL	☒ YES · NO			
HOOK	25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)				3
TIRE WEAR		☒ FAIR · WORN · UNEVEN WEAR		
COMMENT				
OUTRIGGERS				
OUTRIGGERS	X · ☒ H			
OUTRIGGERS COND.	☒ FAIR · Attn			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
COMMENT				
リターダーにじみあり RETARDER: OIL OOZING				
*1 ミッションケースにじみあり TRANSMISSION CASE: OIL OOZING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。