

INSPECTION SHEET 検品書

OTHER その他

INSPECTION DATE	2025/10/30	CATEGORY	自走式破砕機 MOBILE CRUSHER			
MAKE	KOMATSU			MODEL	PC128UU-1	
SERIAL	1839			STAMP	PC128-1839	
HR METER	4702	HR	Odometer	km	YEAR	1995 YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS	TIRE

ENGINE	MODEL			S/N		
Oil leakage	FAIR	Attn		Oil	FAIR	Attn
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	FAIR	Attn
Sound	FAIR	Attn		EPA	YES	NO

CONDITION	FAIR	Attn	
油圧掛かる音がするが上物すべて動作しない IMPLEMENTS: NOT MOVING EVEN SOUNDS LIKE HYDRAULIC PRESSURE APPLYING			
破砕機制御盤ケーブル外れあり、電源入らない CRUSHER CONTROL PANEL CABLES: NOT ATTACHED, UNABLE TO TURN ON			

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
ヒーター風出ない HEATER: NOT BLOWING AIR			
破砕機 CRUSHER NKE-40-20074			
破砕機Fシリンダー外れあり FRONT CYLINDER OF CRUSHER: NOT ATTACHED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。