

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE		2025/10/30		MAKE		TADANO		MODEL		AT-121-3	
SERIAL No.		PLATE : HJ2294				STAMP :		HJ2294			
HR METER		4138		HR		Odometer		14091		km	
YEAR		2012		YR							
CHASSIS		MODEL TKG-NKR85N				No.		7027841			
SHOE						TIRE SIZE		205/85R16			
MAX HIGHT		11.9				m		MAX WEIGHT		200	
								kg			

ENGINE : MODEL		4JJ1		S/N		316215	
Oil leakage	☐ FAIR	☐ Attn					
Blow-By	☐ FAIR	☐ Attn		A LITTLE · MIDDLE · SEVERE			
Sound	☐ FAIR	☐ Attn					
Oil	☐ FAIR	☐ Attn					
Exhaust Color	☐ FAIR	☐ Attn					
US EPA	YES	☐ NO					
OPERATION PUMP							
Sound	FAIR	☐ Attn		*1			
Oil leakage	FAIR	☐ Attn		*1			
Power	FAIR	☐ Attn		*1			
COOLING SYSTEM							
Radiator	☐ FAIR	☐ Attn					
Oil Cooler	FAIR	☐ Attn					
TRANSMISSION & TRAVEL							
T/M TYPE	AT	☐ MT		No. OF GEARS		6 GEARS	
Transmission	☐ FAIR	☐ Attn					
4WD	4WD	☐ 2WD					
Travel	☐ FAIR	☐ Attn					
Swing	FAIR	☐ Attn					
FOOT BRAKE	☐ FAIR	☐ Attn					
PARKING BRAKE	☐ FAIR	☐ Attn					
BOOM							
No. of Section	3	SECTIONS					
DERRICKING CYL.	FAIR	☐ Attn		*1			
EXTENSION CYL.	FAIR	☐ Attn		*1			

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	☐ FAIR	· DIRTY
Operator's Seat	☐ FAIR	☐ Attn	
Glasses	☐ FAIR	☐ Attn	
AirCon	☐ A/C	· H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1
TIRE WEAR	FAIR	☐ WORN	· UNEVEN WEAR
COMMENT			
OUTRIGGERS	X	☐ H	
OUTRIGGERS COND.	FAIR	☐ Attn	*1
COMMENT			
シャーシ刻印腐食のため不明 CHASSIS STAMP: UNREADABLE (CORRODED)			
警告灯多数点灯あり MANY WARNING LAMPS: ON			
*1 PTO入らないため動作未確認 NOT CHECKED (PTO: NOT ENGAGING)			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。