

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/22	MAKE	KOMATSU	MODEL	PC200-8N1
SERIAL	357080			STAMP	KMTPC197K02357080
HR METER	6206	HR	YEAR	2013	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 6D107E-1 S/N 26616302	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES · ☒ NO
MAIN PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
OPERATING SYSTEM	
Swing	☒ FAIR · Attn
Travel	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn 破れあり TORN
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	☒ FAIR · Attn
Boom Cylinder	☒ FAIR · Attn
Arm	☒ FAIR · Attn ヘコミあり DENT
Arm Cylinder	☒ FAIR · Attn
ATTACHMENT	☒ FAIR · Attn ガタあり LOOSE
BKT Cylinder	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

作業 コード	作番	サービス メータ	作業場所 区分	概要	売上日
SE	C01770312	2576	工場	車両洗車	2017/08/07
FA	C017X0019	2576	工場	ツース交換	2017/10/06
FA	C017Z0066	2577	工場	出庫準備	2017/12/15
FA	C01840065	2583	工場	特定自主検査・クレーン定期自主検査	2018/04/11
FA	C01840098	2583	工場	レンタル出庫整備	2018/04/19
FA	C01850281	2626	工場	レンタル機入庫点検・整備	2018/05/30
FA	C018X0130	2912	フィールド	レンタル機入庫点検・整備	2018/10/26
FA	C018X0143	2915	フィールド	レンタル機・出庫点検準備	2019/05/09
AD	C018X0195	2918	工場	レンタル機点検・整備	2018/10/24
FA	C018Z0223	3210	工場	レンタル機入庫点検・整備	2019/01/30
AD	C018Z0284	3250	工場	レンタル機・各部点検整備	2018/12/25
FA	C018Z0293	3210	フィールド	レンタル出庫・点検整備	2019/01/30
FA	C01920317	3473	フィールド	レンタル機整備・（ツース盤交換）	2019/03/08
FA	C01930321	3548	フィールド	特定自主検査・クレーン定期自主検査	2019/04/09
FA	C01930322	3548	フィールド	レンタル機・メンテナンス一式	2019/04/09
FA	C01970299	3821	フィールド	レンタル機入庫点検・整備	2019/08/22
AD	C01970323	3822	工場	レンタル機・追加修理一式	2019/07/31
FA	C01980346	3823	フィールド	レンタル出庫・点検整備	2019/09/26
FA	C019X0211	4061	フィールド	レンタル機・メンテナンス一式	2019/11/27
AD	C02010034	4264	フィールド	スィベル油漏れ修理一式	2020/01/16
FA	C02020300	4418	フィールド	レンタル機・特定自主検査	2020/03/10
FA	C02020301	4418	フィールド	レンタル機・オイル交換一式	2020/03/10
CA	C0203A46	0		フロアガラス	2020/03/09
CA	C0206B88	0		シューボルト・ナット各 1 0 個	2020/06/23
FA	C02070128	4892	フィールド	レンタル機・オイル交換一式	2020/07/27
FA	C02070387	5090	フィールド	レンタル機・メンテナンス	2020/09/30
FA	C02080228	4982	フィールド	レンタル機・エアコン不良点検	2020/08/31
FA	C020X0421	5169	フィールド	レンタル機・メンテナンス一式	2020/10/30
FA	C02140232	2578	工場	外装修理一式ほか	2022/07/29
FA	C02210155	5207	工場	外装修理一式ほか	2022/08/04
FA	Z022Z0023	5208	フィールド	K F 2 0 0 0 4 3 特定自主検査 クレーン検査	2022/12/14
FA	Z02310004	5208	フィールド	K F 2 0 0 0 4 3 出庫点検	2023/01/10
FA	D02350465	5495	フィールド	ワイパーウォッシュホース損傷点検・修理	2023/06/12
FA	D02360060	550	フィールド	エアコン作動不調点検・修理	2023/06/12
FA	D02380054	5625	工場	レンタル機入庫点検	2023/08/10
FA	D02380067	5625	工場	油脂類交換、他	2023/08/10
FA	D02380068	5629	工場	特定自主検査、アームクレーン定期自主検査	2023/08/22
FA	D02380294	5631	工場	法面バケット取付け	2023/08/31
AD	D023Z0068	5779	フィールド	バケットリングピン曲がり点検・修理	2024/02/07
FA	D023Z0238	5785	工場	レンタル機入庫点検、他	2024/01/31
AD	D02410482	0	工場	外装部分塗装修正、他	2024/03/28
FA	D02460088	5789	工場	レンタル機出庫点検	2024/06/10
FA	D02480114	6035	フィールド	特定自主検査、アームクレーン定期自主検査 1 年	2024/08/08
FA	D024X0482	0	工場	レンタル機入庫点検、車両洗車	2024/11/27
FA	D02510400	6197	工場	油脂類交換	2025/02/13