

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/21	MAKE	KOMATSU	MODEL	PC200-10
SERIAL	455693		STAMP	KMTPC243AHC455693	
HR METER	7711	HR	YEAR	2017	YR
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 6D107E-2 S/N 26662134	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES · ☒ NO
MAIN PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
OPERATING SYSTEM	
Swing	☒ FAIR · Attn
Travel	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	☒ FAIR · Attn
Boom Cylinder	☒ FAIR · Attn
Arm	☒ FAIR · Attn
Arm Cylinder	☒ FAIR · Attn
ATTACHMENT	☒ FAIR · Attn ガタ大 MUCH LOOSE
BKT Cylinder	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

作業 コード	作番	サービス メータ	作業場所区分	概要	売上日
FA	C02180325	2,980	フィールド	レンタル機・メンテナンス	2021/10/21
FA	C021X0226	2,980	フィールド	特定自主検査・クレーン定期検査	2021/10/28
AD	C021X0301	2,977	工場	中古車コマツケア・2 0 0 0 Hメンテ	2021/11/04
FA	C021Y0162	2,984	フィールド	レンタル機・バッテリー交換ほか	2021/11/18
FA	C021Y0476	2,987	フィールド	レンタル機・バケット入れ替え	2021/11/29
FA	B02240080	3,248	工場	K F 2 0 0 0 9 7 入庫点検	2022/04/18
FA	B02240406	3,250	工場	移動レンタル機整備	2022/05/24
BA	B02250333	3,248	フィールド	キャブ天窓から水漏れ改修 A T 2 2 0 0 6	2022/06/03
FA	B02260210	3,253	工場	K F 2 0 0 0 9 7 出庫点検	2022/06/08
FA	B02270001	3,365	工場	K F 2 0 0 0 9 7 入庫点検	2022/07/07
BL	B02270397	3,365	工場	中古車コマツケア 1 回目	2022/08/03
FA	B02270144	3,365	工場	自社レンタル機メンテナンス	2022/07/25
FA	B02270145	3,365	工場	返却レンタル機不具合部補修	2022/07/13
FA	B022X0118	3,798	フィールド	特定自主検査・クレーン検査	2022/10/18
BL	B022X0119	3,798	工場	中古車コマツケア 2 回目	2022/10/18
FA	B022X0120	3,798	フィールド	オイルメンテナンス	2022/10/18
AD	B022X0377	0	フィールド	バケット ロックボルト、ナット各 2 セット納品	2022/10/25
FA	B022Z0469	4,074	フィールド	K F 2 0 0 0 9 7 入庫点検	2023/01/06
BL	B02310091	4,076	工場	ケア K D P F 交換	2023/01/13
FA	B02310390	4,079	工場	返却レンタル機補修	2023/03/02
FA	B02310391	4,079	工場	自社レンタル機補修	2023/03/02
FA	B02320506	4,079	工場	出庫点検・ツース盤交換	2023/03/24
FA	B02350083	4,254	フィールド	5 0 0 H オイルメンテナンス	2023/05/15
FA	B02380242	4,708	フィールド	オイルメンテナンス	2023/09/16
FA	B02390121	4,708	フィールド	特定自主検査・クレーン検査	2023/09/16
FA	B02390272	4,708	フィールド	特定自主検査時使用部品	2023/09/15
FA	B023Z0076	4,935	工場	入庫点検	2023/12/08
FA	B023Z0154	4,938	工場	自社レンタル機メンテナンス	2023/12/11
FA	B02430150	5,140	工場	自社レンタル機メンテナンス	2024/04/15
FA	B02430176	5,135	工場	入庫点検	2024/03/12
AD	B02430500	5,140	工場	返却レンタル機不具合補修	2024/04/15
FA	B02430501	5,138	工場	自社レンタル機メンテナンス	2024/04/11
FA	B02440320	5,140	工場	出庫点検	2024/04/19
FA	B02450148	0	フィールド	グリスニップル不良、グリスガン不良交換	2024/09/30
FA	B02460452	4,752	フィールド	バケットサイドカッター交換	2024/07/19
FA	B02480109	5,786	フィールド	1 0 0 0 H オイルメンテナンス	2024/08/29
CA	B0248A38	0		ツース盤 納品	2024/08/20
FA	B02490232	5,941	フィールド	シューボルト交換	2024/09/30
FA	B02490386	5,941	フィールド	特自検 1 年・クレーン検査	2024/09/30
FA	B024X0312	6,054	フィールド	グリスノズル交換	2024/10/22
AD	B024Z0009	6,312	フィールド	ツース盤交換	2024/12/24
FA	B024Z0010	6,322	フィールド	5 0 0 H オイルメンテナンス	2024/12/10
FA	B02530056	6,870	フィールド	2 0 0 0 H オイルメンテナンス	2025/03/25
FA	B02550227	7,178	フィールド	ウェイト付近油漏れ点検	2025/05/23
FA	G02590057	7,707	工場	燃料ホース劣化漏れ	2025/09/18