

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/21	MAKE	KOMATSU	MODEL	PC200-10
SERIAL	455512		STAMP	KMTPC243JGC455512	
HR METER	4553	HR	YEAR	2017	YR
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 6D107E-2 S/N 26659654	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES · ☒ NO
MAIN PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
OPERATING SYSTEM	
Swing	☒ FAIR · Attn
Travel	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	☒ FAIR · Attn
Boom Cylinder	☒ FAIR · Attn
Arm	☒ FAIR · Attn
Arm Cylinder	☒ FAIR · Attn
ATTACHMENT	☒ FAIR · Attn
BKT Cylinder	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	YES · ☒ NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO Breaker only · ☒ Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

作業 コード	作番	サービス メータ	作業場所 区分	概要	売上日
FA	A01840291	781	フィールド	特定自主検査（4月13日完了）	2018/04/23
FA	A018X0559	1,115	フィールド	1 0 0 0 Hメンテ	2018/11/02
FA	A01930206	1,282	フィールド	特定自主検査（3月8日完了）	2019/03/15
FA	A02020148	1,687	フィールド	エンジン回転不調点検	2020/02/17
FA	A02020319	1,756	フィールド	特定自主検査	2020/03/05
FA	A02020329	1,817	フィールド	バケット亀裂修理	2020/03/19
FA	A02050195	2,033	フィールド	2 0 0 0 Hメンテナンス	2020/05/25
AD	A02070097	2,130	工場	バケットフック溶接交換	2020/07/07
FA	A020Z0109	2,434	フィールド	5 0 0 Hメンテナンス	2020/12/15
FA	A02120099	2,612	フィールド	特定自主検査	2021/02/18
FA	A02180115	5,992	フィールド	1 0 0 0 Hメンテナンス	2021/08/25
FA	A02210484	3,445	フィールド	特定自主検査、5 0 0 Hメンテナンス	2022/01/29
FA	A02220004	0	工場	ツース摩耗交換	2022/02/02
FA	A02270017	3,805	フィールド	油圧ホース交換	2022/07/20
BJ	A02280299	4,026	フィールド	コマツケアK D P F 交換	2022/09/21
FA	A02280302	4,026	フィールド	2 0 0 0 Hメンテナンス	2022/08/30
FA	A02280348	4,176	工場	各ベルト交換	2022/10/21
FA	A02290227	0	フィールド	バケットロックボルト（短）折損脱落	2022/09/13
FA	A02320218	4,443	フィールド	特定自主検査、5 0 0 Hメンテナンス	2023/02/28
FA	A02440318	4,549	工場	不具合箇所修理（K F 2 0 0 0 4 9）	2024/07/20
FA	A02470086	4,549	工場	特定自主検査	2024/07/19