

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                                                         |      |         |                   |          |
|-----------------|-------------------------------------------------------------------------|------|---------|-------------------|----------|
| INSPECTION DATE | 2025/10/24                                                              | MAKE | KOMATSU | MODEL             | PC200-10 |
| SERIAL          | 455114                                                                  |      | STAMP   | KMTPC243HGC455114 |          |
| HR METER        | 6028                                                                    | HR   | YEAR    | 2016              | YR       |
| CAB/CNP         | <input checked="" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 600G              |          |

|                                                    |                                                                         |
|----------------------------------------------------|-------------------------------------------------------------------------|
| <b>ENGINE : MODEL</b> 6D107E-2 <b>S/N</b> 26656147 |                                                                         |
| Oil leakage                                        | <input checked="" type="radio"/> FAIR · Attn                            |
| Blow-By                                            | <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound                                              | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil                                                | <input checked="" type="radio"/> FAIR · Attn                            |
| Exhaust Color                                      | <input checked="" type="radio"/> FAIR · Attn                            |
| US EPA                                             | YES · <input checked="" type="radio"/> NO                               |
| <b>MAIN PUMP</b>                                   |                                                                         |
| Sound                                              | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil leakage                                        | <input checked="" type="radio"/> FAIR · Attn                            |
| Power                                              | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>COOLING SYSTEM</b>                              |                                                                         |
| Radiator                                           | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil Cooler                                         | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>OPERATING SYSTEM</b>                            |                                                                         |
| Swing                                              | <input checked="" type="radio"/> FAIR · Attn                            |
| Travel                                             | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>INTERIOR</b> See Photos. 写真参照                   |                                                                         |
| INTERIOR COND.                                     | CLEAN · <input checked="" type="radio"/> FAIR · DIRTY                   |
| Operator's Seat                                    | <input checked="" type="radio"/> FAIR · Attn 破れあり TOO MUCH WORN         |
| Glasses                                            | <input checked="" type="radio"/> FAIR · Attn                            |
| AirCon                                             | <input checked="" type="radio"/> A/C · H/C · H only · C only · None     |
| <b>BOOM / ARM / BKT</b>                            |                                                                         |
| Boom                                               | <input checked="" type="radio"/> FAIR · Attn                            |
| Boom Cylinder                                      | <input checked="" type="radio"/> FAIR · Attn                            |
| Arm                                                | <input checked="" type="radio"/> FAIR · Attn                            |
| Arm Cylinder                                       | <input checked="" type="radio"/> FAIR · Attn                            |
| ATTACHMENT                                         | <input checked="" type="radio"/> FAIR · Attn                            |
| BKT Cylinder                                       | <input checked="" type="radio"/> FAIR · Attn                            |

|                                                                      |                                                                              |
|----------------------------------------------------------------------|------------------------------------------------------------------------------|
| <b>UNDERCARRIAGE :</b> See Photos. 写真参照                              |                                                                              |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 3                                                                            |
| <b>COMMENT</b>                                                       |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
| BKT                                                                  | <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                | LONG · <input checked="" type="radio"/> WRIST                                |
| Multi                                                                | <input checked="" type="radio"/> MULTI · 2 · NO                              |
| ARM-CRANE                                                            | <input checked="" type="radio"/> YES · NO                                    |
| BLADE                                                                | YES · <input checked="" type="radio"/> NO                                    |
| OFFSET                                                               | YES · <input checked="" type="radio"/> NO                                    |
| OFFSET Cylinder                                                      | FAIR · Attn                                                                  |
| Piping                                                               | YES · <input checked="" type="radio"/> NO Breaker only · Multi               |
| <b>COMMENT</b>                                                       |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4                                                                            |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

| 作業<br>コード | 作番        | サービス<br>メータ | 作業場所区分 | 概要                                | 売上日        |
|-----------|-----------|-------------|--------|-----------------------------------|------------|
| AD        | A02080143 | 2158 フィールド  |        | 委託中古車受入点検                         | 2020/08/27 |
| AD        | D020Y0512 | 2168 フィールド  |        | 2 0 0 0 Hリセットメンテ                  | 2020/12/14 |
| FA        | D020Y0513 | 2168 フィールド  |        | エアコン点検（フロンガス点検）                   | 2020/12/05 |
| FA        | D020Z0035 | 2169 フィールド  |        | 特定自主検査、アームクレーン定期自主検査              | 2020/12/05 |
| FA        | D020Z0082 | 2169 フィールド  |        | バケットツース交換                         | 2020/12/11 |
| FA        | D02150367 | 3215 フィールド  |        | 油脂類交換（1 0 0 0 H）                  | 2021/06/09 |
| FA        | D021X0348 | 3704 工場     |        | 特定自主検査、アームクレーン定期自主検査              | 2021/10/26 |
| FA        | D021X0349 | 3704 工場     |        | エンジンオイル及びエレメント交換                  | 2021/10/26 |
| FA        | D021X0374 | 3704 工場     |        | レンタル機入庫点検                         | 2021/10/29 |
| AD        | D021Y0158 | 3707 工場     |        | バケットシリンダー脱着OV（油洩れ）                | 2021/11/22 |
| FA        | D021Y0159 | 3706 工場     |        | バケットA s s y入替え、他                  | 2021/11/22 |
| FA        | D02250111 | 3709 工場     |        | レンタル機出庫点検、他                       | 2022/05/20 |
| FA        | D02280444 | 3733 工場     |        | レンタル機入庫点検、他                       | 2022/10/11 |
| FA        | Z022Y0019 | 3734 フィールド  |        | K F 2 0 0 0 8 5 入庫点検              | 2022/12/07 |
| FA        | Z022Y0030 | 3734 工場     |        | K F 2 0 0 0 8 5 P A B ツース盤、グリスポンプ | 2022/11/30 |
| FA        | Z022Y0080 | 3734 フィールド  |        | マルチバルブ油漏れ修理                       | 2022/11/25 |
| FA        | Z022Z0016 | 3734 フィールド  |        | K F 2 0 0 0 8 5 特定自主検査 クレーン検査     | 2022/12/14 |
| AD        | D02340017 | 3744 フィールド  |        | スケルトンバケット取付け、他                    | 2023/04/06 |
| AD        | D02340186 | 3735 工場     |        | スケルトンバケット～S T Dバケットへ入替え           | 2023/04/17 |
| FA        | D02340187 | 3735 工場     |        | レンタル機入庫点検、他                       | 2023/04/17 |
| BJ        | Z02350026 | 4000 フィールド  |        | K F 2 0 0 0 8 5 K D P F 交換        | 2023/06/05 |
| FA        | Z02350027 | 3793 フィールド  |        | K F 2 0 0 0 8 5 K C C V 交換        | 2023/05/29 |
| FA        | D02360108 | 3820 フィールド  |        | ポンプ～作動油タンク間低圧ホース交換                | 2023/06/08 |
| FA        | D023Z0065 | 5066 フィールド  |        | 油脂類交換                             | 2023/12/20 |
| FA        | D023Z0131 | 5066 フィールド  |        | 特定自主検査、アームクレーン定期自主検査              | 2023/12/18 |
| AD        | D023Z0165 | 5066 フィールド  |        | バケットツース交換、他                       | 2023/12/18 |
| FA        | D023Z0242 | 5218 フィールド  |        | アーム角度センサー損傷交換                     | 2024/01/12 |
| FA        | D02430061 | 5683 フィールド  |        | 油脂類交換（5 0 0 H）                    | 2024/03/18 |
| FA        | D02440136 | 5823 フィールド  |        | エラーコード表示点検・修理（C A 2 2 7 2）        | 2024/04/15 |
| FA        | D02450081 | 6001 工場     |        | レンタル機入庫点検、他                       | 2024/05/30 |
| FA        | D02450369 | 0 工場        |        | ワイパーブレード交換                        | 2024/07/25 |
| FA        | Z02460029 | 6006 フィールド  |        | バケットガタ修理及びアームクレーンフック交換            | 2024/07/23 |
| FA        | Z02460056 | 6006 フィールド  |        | K F 2 0 0 0 8 5 定期エレメント交換         | 2024/07/23 |