

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/29	MAKE	CAT	MODEL	320E-2
SERIAL	CAT0320ECSXE02129			STAMP	CAT0320ECSXE02129
HR METER	9156 / 9158	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL C6.6		S/N C8N31244	
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn A LITTLE • MIDDLE • SEVERE	
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	☒ YES	NO	
MAIN PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
OPERATING SYSTEM			
Swing	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • ☒ FAIR •	DIRTY	
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn Fびび割れあり UPPER WINDSHIELD: CRACKED	
AirCon	☒ A/C •	H/C • H only • C only • None	
BOOM / ARM / BKT			
Boom	☒ FAIR	Attn	
Boom Cylinder	☒ FAIR	Attn	
Arm	☒ FAIR	Attn	
Arm Cylinder	☒ FAIR	☒ Attn 油漏れあり OIL LEAKING	
ATTACHMENT	☒ FAIR	Attn	
BKT Cylinder	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT ☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER () Lever LONG • ☒ WRIST Multi ☒ MULTI • 2 • NO ARM-CRANE YES • ☒ NO BLADE YES • ☒ NO OFFSET YES • ☒ NO OFFSET Cylinder FAIR • Attn Piping ☒ YES • NO Breaker only ☒ Multi	
COMMENT	
マフラー排出口腐食あり MUFFLER EXHAUST PIPE: CORRODED & HUGE HOLES バケットとブームが干渉する BUCKET: ABLE TO INTERFERE WITH BOOM	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。