

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/10	MAKE	TADANO	MODEL	TR-250M-6
SERIAL No.	PLATE : FB2281			STAMP : TR255-0809	
HR METER	11734	HR	Odometer	3461	km
TIRE SIZE	385/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☐ Attn ☐	*1
Blow-By	FAIR ☐ Attn ☐	A LITTLE ☐ MIDDLE ☒ SEVERE ☐
Sound	FAIR ☐ Attn ☐	
Oil	FAIR ☐ Attn ☐	
Exhaust Color	FAIR ☐ Attn ☐	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	FAIR ☐ Attn ☐	
Oil leakage	FAIR ☐ Attn ☐	
Power	FAIR ☐ Attn ☐	
COOLING SYSTEM		
Radiator	FAIR ☐ Attn ☐	
Oil Cooler	FAIR ☐ Attn ☐	
OPERATING SYSTEM		
Computer	OK ☐ NG ☐	*2
Swing	FAIR ☐ Attn ☐	
Travel	FAIR ☐ Attn ☐	*3
TRANSMISSION		
Transmission	FAIR ☐ Attn ☐	*4
No. OF GEARS	4 GEARS	
4WD	4WD ☐ 6WD ☐	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ FAIR ☒ DIRTY ☐	
Operator's Seat	FAIR ☐ Attn ☐	破れあり HUGE CUTS
Glasses	FAIR ☐ Attn ☐	
AirCon	A/C ☒ H/C ☐ H only ☐ C only ☐ None ☐	
COMMENT		
ミラー張り出し不可		
FRONT OUTER REAR-VIEW MIRRORS: UNABLE TO UNFOLD		

BOOM				
No. of Section	4	SECTIONS		
CRACK/ENFORCEMENT	FAIR ☐ Attn ☐			
DERRICKING CYL.	FAIR ☐ Attn ☐	傷あり SCRATCHED		
EXTENSION CYL.	FAIR ☐ Attn ☐			
JIB	YES ☐ NO ☐			
JIB TYPE	STD ☐ PWR ☐			
MAIN & SUB WIRE	YES ☐ NO ☐	*5		
FREE FALL	YES ☐ NO ☐			
HOOK	25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				2
TIRE WEAR		FAIR ☒ WORN ☐ UNEVEN WEAR ☐		
COMMENT				
OUTRIGGERS				
OUTRIGGERS	X ☒ H ☐			
OUTRIGGERS COND.	FAIR ☐ Attn ☐			
Oil leakage (JACK CYL.)	FRONT	L ☐ R ☐	REAR	L ☐ R ☐
Oil leakage (SLIDE CYL.)	FRONT	L ☐ R ☐	REAR	L ☐ R ☐
COMMENT				
*1 E/G下部油漏れあり BOTTOM OF ENGINE: OIL LEAKING				
*2 画面劣化のため見えない MONITOR: VERY BLURRED (DETERIORATED)				
*3 リアステアロック不可 REAR STEERING LOCK: MALFUNCTION				
*4 リアステアロック不良のため変速できない				
*4 UNABLE TO CHANGE GEARS (REAR STEERING LOCK: MALFUNCTION)				
*5 補ウインチモーター油漏れあり				
*5 AUXILIARY HOISTING WINCH MOTOR: OIL LEAKING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。