

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/22	MAKE	BOBCAT	MODEL	7753
SERIAL	509631980	STAMP	NOT FOUND		
HR METER	5308	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / (ROPS CNP) / CNP / NONE	TIRE SIZE	10-16.5	YEAR	1993 YR

ENGINE : MODEL V2203 S/N 69084	
Oil leakage	(FAIR) • Attn
Blow-By	(FAIR) • Attn A LITTLE • MIDDLE • SEVERE
Sound	(FAIR) • Attn
Oil	(FAIR) • Attn
Exhaust Color	(FAIR) • Attn
US EPA	YES • (NO)
OPERATION PUMP	
Sound	(FAIR) • Attn
Oil leakage	(FAIR) • Attn
Power	(FAIR) • Attn
COOLING SYSTEM	
Radiator	(FAIR) • Attn
Oil Cooler	(FAIR) • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	(PS) • DD
Transmission	(FAIR) • Attn
Travel	FAIR • (Attn) *1
FOOT BRAKE	FAIR • Attn
PARKING BRAKE	FAIR • (Attn) 効かない MALFUNCTION
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • (FAIR) • DIRTY
Operator's Seat	(FAIR) • Attn
Glasses	(FAIR) • Attn
AirCon	A/C • H/C • H only • C only • (None)
FRONT & CYLINDERS	
Arm	FAIR • (Attn) *2
Bell crank	(FAIR) • Attn
Bucket	(FAIR) • Attn
Articulate	FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	(FAIR) • WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / (LEVER STEERING)	
RIDE CONTROL	YES • (NO)
ATTACHMENTS	
STD BKT	(YES) • OTHER
BLADE	YES • (NO) Piping for Tilt YES • (NO)
COMMENT	
*1 レバー中立でも少しずつ前進する	
*1 A LITTLE TRAVELING FORWARD	
EVEN LEVER STEERING IS A NEUTRAL POSITION	
*2 左シリンダーホースひび割れあり	
*2 LEFT CYLINDER HOSE: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。