

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/27	MAKE	CAT	MODEL	320GC-07B
SERIAL	CAT00320HKTN10048			STAMP	CAT00320HKTN10048
HR METER	6638	HR	YEAR	2018	YR
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		C4.4	S/N	W7N47817
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	左右にじみあり CYLINDERS: OIL OOZING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :		See Photos.	写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER(		
Lever	LONG ▪ (WRIST)		
Multi	(MULTI) ▪ 2 ▪ NO		
ARM-CRANE	YES ▪ (NO)		
BLADE	YES ▪ (NO)		
OFFSET	YES ▪ (NO)		
OFFSET Cylinder	FAIR ▪ Attn		
Piping	YES ▪ (NO)	Breaker only ▪ Multi	
COMMENT			
排気ガス浄化システム異常表示あり			
WARNING DISPLAY FOR EXHAUST GAS CLEANING SYSTEM			
E/G異常表示あり ENGINE WARNING DISPLAY			
ウォーターセパレータ満水表示あり			
WARNING DISPLAY FOR WATER SEPARATOR FULL CONDITION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。