

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/10	MAKE	TADANO	MODEL	GR-160N-2
SERIAL No.	PLATE :	526496	STAMP :	T006-0382	
HR METER	24536	HR	Odometer	153086	km
TIRE SIZE	325/95R24		YEAR		YR

ENGINE : MODEL		S/N	
Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	
TRANSMISSION			
Transmission	FAIR	Attn	
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR •	DIRTY	
Operator's Seat	FAIR	Attn	破れあり HUGE CUTS
Glasses	FAIR	Attn	
AirCon	A/C •	H/C • H only • C only • None	
COMMENT			

BOOM					
No. of Section	6	SECTIONS			
CRACK/ENFORCEMENT	FAIR	▪ Attn			
DERRICKING CYL.	FAIR	▪ Attn			
EXTENSION CYL.	FAIR	▪ Attn			
JIB	YES	▪ NO			
JIB TYPE	STD	▪ PWR			
MAIN & SUB WIRE	YES	▪ NO			
FREE FALL	YES	▪ NO			
HOOK	16t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR				
COMMENT					
左Fバンパーヘコミあり LEFT PART OF FRONT BUMPER: MUCH DENT					
OUTRIGGERS					
OUTRIGGERS	X	• H			
OUTRIGGERS COND.	FAIR	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L • R	REAR	L • R	
Oil leakage (SLIDE CYL.)	FRONT	L • R	REAR	L • R	
COMMENT					
*1 E/G下周りにじみあり BOTTOM OF ENGINE: OIL OOZING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。