

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2025/10/17	MAKE	S MAC	MODEL	RH120		
SERIAL No.	PLATE : 00032			STAMP : 00032			
HR METER	2502	HR	Odometer	–	km	YEAR	YR
CHASSIS	MODEL –			No. –			
SHOE				TIRE SIZE	UNKNOWN		
MAX HIGHT	12.0			m	MAX WEIGHT	250	kg

ENGINE :		MODEL	S/N	
Oil leakage	(FAIR) · Attn			
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR) · Attn			
Oil	(FAIR) · Attn			
Exhaust Color	(FAIR) · Attn			
US EPA	YES (NO)			
OPERATION PUMP				
Sound	(FAIR) · Attn			
Oil leakage	(FAIR) · Attn			
Power	(FAIR) · Attn			
COOLING SYSTEM				
Radiator	(FAIR) · Attn			
Oil Cooler	(FAIR) · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	(AT) · MT	No. OF GEARS	2 GEARS	
Transmission	(FAIR) · Attn			
4WD	4WD · 2WD			
Travel	(FAIR) · Attn			
Swing	(FAIR) · Attn			
FOOT BRAKE	(FAIR) · Attn			
PARKING BRAKE	(FAIR) · Attn			
BOOM				
No. of Section	3	SECTIONS		
DERRICKING CYL.	(FAIR) · Attn			
EXTENSION CYL.	(FAIR) · Attn			

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	(FAIR) · Attn		
Glasses	(FAIR) · Attn		
AirCon	A/C · H/C · H only · C only · (None)		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
TIRE WEAR	(FAIR) · (WORN) · UNEVEN WEAR		
COMMENT			
OUTRIGGERS	X · H		
OUTRIGGERS COND.	(FAIR) · Attn		
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。