

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/16	MAKE	KUBOTA	MODEL	RX-205
SERIAL	KBCPZ36AAL3D22678			STAMP	KBCPZ36AAL3D22678
HR METER	834	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE			SHOE	250G PADS

ENGINE : MODEL D1105 S/N 1LF5254	
Oil leakage	<u>FAIR</u> • Attn
Blow-By	<u>FAIR</u> • Attn A LITTLE • MIDDLE • SEVERE
Sound	<u>FAIR</u> • Attn
Oil	<u>FAIR</u> • Attn
Exhaust Color	<u>FAIR</u> • Attn
US EPA	YES • <u>NO</u>
MAIN PUMP	
Sound	<u>FAIR</u> • Attn
Oil leakage	<u>FAIR</u> • Attn
Power	<u>FAIR</u> • Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> • Attn
Oil Cooler	<u>FAIR</u> • Attn
OPERATING SYSTEM	
Swing	<u>FAIR</u> • Attn
Travel	<u>FAIR</u> • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY
Operator's Seat	<u>FAIR</u> • Attn
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • <u>None</u>
BOOM / ARM / BKT	
Boom	<u>FAIR</u> • Attn
Boom Cylinder	<u>FAIR</u> • Attn
Arm	<u>FAIR</u> • Attn
Arm Cylinder	<u>FAIR</u> • Attn
ATTACHMENT	<u>FAIR</u> • Attn
BKT Cylinder	<u>FAIR</u> • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	<u>MULTI</u> • 2 • NO
ARM-CRANE	<u>YES</u> • NO
BLADE	<u>YES</u> • NO
OFFSET	<u>YES</u> • NO
OFFSET Cylinder	<u>FAIR</u> • Attn
Piping	YES • <u>NO</u> Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。