

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/10/30	MAKE	CAT	MODEL	D3C
SERIAL	5CJ00159			STAMP	5CJ00159
HR METER	3590	HR	SHOE	630LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	45V94604
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · DD	DIFF. STEERING	YES · NO
Transmission	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BLADE & CYLINDERS			
BLADE	FAIR · Attn		
CYLD.(R)	FAIR · Attn		
CYLD.(L)	FAIR · Attn		
TILT CYLD	FAIR · Attn		
ANGLE CYLD	FAIR · Attn	*1	

UNDERCARRIAGE		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT 下周り油汚れあり BOTTOM: OIL STAINS			
Ripper	MULTI ▪ S/S	Shanks	PCS
Ripper CYLD.	FAIR ▪ Attn		
COMMENT ヒーターノブ固着あり、動作不可 HEATER SWITCH: STUCK, HEATER: UNABLE TO OPERATE *1 左右メッキ剥がれあり CYLINDERS: COATING PEELED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。