

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2025/10/23	MAKE	YANMAR	MODEL	C12R-B	
SERIAL	28573			STAMP	28573	
HR METER	909	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	230R	TIRE

ENGINE : MODEL		2TE67L	S/N	18554
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
OPERATION PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	PS	DD	No. OF GEARS	— GEARS
Transmission	FAIR	Attn		
Travel	FAIR	Attn		
Swing	FAIR	Attn		
Articulate	FAIR	Attn		
FOOT BRAKE	FAIR	Attn		
PARKING BRAKE	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
				None

MAIN FRAME					
MAIN FLAME		FAIR	▪	Attn	
VESSEL					
VESSEL		FAIR	▪	Attn	
REAR GATE TYPE		NORMAL	▪	L-GATE (FLAT)	
REAR GATE		FAIR	▪	Attn	
UNDERCARRIAGE: See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR			
COMMENT					
アクセルレバー高アイドルにするとローアイドルに戻らない (アクセルワイヤーを戻せばローアイドルになる) UNABLE TO CHANGE TO LOW IDLING FROM HIGH IDLING BY THE ACCELERATOR LEVER (ABLE TO CHANGE BY THE ACCELERATOR WIRE)					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。