

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/22	MAKE	KATO	MODEL	HD308US-6
SERIAL	KWJ28E01EF0005125		STAMP	5125	
HR METER	2854	HR	YEAR	2015	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		4LE2	S/N	626511
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn			
Travel	FAIR · Attn	*1		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn	ドア下部加工あり LOWER DOOR GLASS: MODIFIED		
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
ATTACHMENT	FAIR · Attn			
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())	
Lever	LONG ▪ (WRIST)	
Multi	MULTI ▪ 2 ▪ (NO)	
ARM-CRANE	(YES) ▪ NO	*2
BLADE	(YES) ▪ NO	
OFFSET	YES ▪ (NO)	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	(YES) ▪ NO	Breaker only ▪ (Multi)
COMMENT		
*1 増速不可 HIGH SPEED MODE: UNABLE TO USE		
*2 ディスプレイ何も点かず、何も反応しないためクレーンモード入らない		
*2 CRANE MODE: UNABLE TO TURN ON		
(MONITOR: NOT DISPLAYING or WORKING)		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。