

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/20	MAKE	HITACHI	MODEL	LX70-7
SERIAL	RYU4F000A00000471			STAMP	S50-00471
HR METER	3229	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE		16.9-24	

ENGINE : MODEL 4BG1 S/N 170865	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	☒ YES · NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS · DD
Transmission	☒ FAIR · Attn 変速しない UNABLE TO SHIFT UP
Travel	☒ FAIR · Attn
FOOT BRAKE	☒ FAIR · Attn
PARKING BRAKE	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn 破れあり TORN
Glasses	☒ FAIR · Attn
AirCon	A/C · H/C · ☒ H only · C only · None
FRONT & CYLINDERS	
Arm	☒ FAIR · Attn
Bell crank	☒ FAIR · Attn
Bucket	☒ FAIR · Attn
Articulate	☒ FAIR · Attn ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt ☒ YES · NO
COMMENT	
右サイドカバーラッチ破損あり RIGHT SIDE COVER LATCH: BROKEN	
スピードメーター不良 SPEED METER: MALFUNCTION	
ヒーター風出ない HEATER: NOT BLOWING AIR	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。