

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2025/10/22	MAKE	KOBELCO	MODEL	SK100W		
SERIAL	YE-01190			STAMP	YE1-1190		
HR METER	8247	HR	Odometer	11685	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	9.00-20		

ENGINE : MODEL 6D31 S/N 016879					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES	(NO)			
MAIN PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
OPERATING SYSTEM					
Swing	(FAIR)	Attn	ガタあり SWING: LOOSE		
Travel	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	· (FAIR) ·	DIRTY		
Operator's Seat	(FAIR)	Attn	破れあり TORN		
Glasses	(FAIR)	Attn			
AirCon	(A/C)	· H/C · H only · C only · None			
BOOM / ARM / BKT					
Boom	(FAIR)	Attn			
Boom Cylinder	FAIR	· (Attn)	左側油漏れあり LEFT CYLINDER: OIL LEAKING		
Arm	(FAIR)	Attn			
Arm Cylinder	(FAIR)	Attn			
ATTACHMENT	(FAIR)	Attn			
BKT Cylinder	(FAIR)	Attn			

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR	(FAIR)	· WORN · UNEVEN WEAR	
COMMENT			
ミッション周り油漏れ小 AROUND TRANSMISSION: OIL LEAKING			
BKT	(STD)	/ SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG	· (WRIST)	
Multi	(MULTI)	· 2 · NO	
ARM-CRANE	YES	· (NO)	
BLADE	YES	· (NO)	
OFFSET	(YES)	· NO	
OFFSET Cylinder	FAIR	· (Attn)	油漏れ小 OIL LEAKING
Piping	YES	· (NO)	Breaker only · Multi
OUTRIGGERS COND.	(FAIR)	· Attn	
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。