

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/21	MAKE	HITACHI	MODEL	ZX225US-5B
SERIAL	HCMDCNA0T00307349		STAMP	HCMDCNA0T00307349	
HR METER	5568	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE :	MODEL	4HK1	S/N	755042
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn	ガタあり SWING: LOOSE		
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
ATTACHMENT	FAIR · Attn	ガタあり LOOSE		
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT 	
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER ())
Lever	LONG ▪ (WRIST)
Multi	(MULTI) ▪ 2 ▪ NO
ARM-CRANE	(YES) ▪ NO
BLADE	YES ▪ (NO)
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	(YES) ▪ NO Breaker only ▪ (Multi)
COMMENT 左Fサイドカバー紐留めあり FRONT LEFT SIDE COVER: FIXED BY SOME ROPE A/Cベルト欠 A/C: NO BELT 	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。