

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/12/1	MAKE	CAT	MODEL	966M
SERIAL	CAT0966MTLMM10259			STAMP	CAT0966MTLMM10259
HR METER	22101	HR	Odometer	58576	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	26.5-25

ENGINE : MODEL C9.3 S/N SYE18430	
Oil leakage	FAIR • ☒ Attn *1
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES • ☒ NO ラベル読み取れない STICKER: UNREADABLE
OPERATION PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS • DD
Transmission	FAIR • Attn
Travel	FAIR • Attn
FOOT BRAKE	FAIR • Attn
PARKING BRAKE	FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY
Operator's Seat	FAIR • Attn
Glasses	FAIR • ☒ Attn Fひび割れあり WINDSHIELD: CRACKED
AirCon	☒ A/C • H/C • H only • C only • None
FRONT & CYLINDERS	
Arm	FAIR • Attn
Bell crank	FAIR • Attn
Bucket	FAIR • Attn
Articulate	FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR • ☒ WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / ☒ LEVER STEERING	
RIDE CONTROL	☒ YES • NO
ATTACHMENTS	
STD BKT	☒ YES • OTHER
BLADE	YES • ☒ NO Piping for Tilt YES • ☒ NO
COMMENT	
*1 オイルパン周り油漏れあり AROUND OIL PAN: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。