

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/10/22	MAKE	CAT	MODEL	D7ELGP
SERIAL	CAT00D7ECSSH00485			STAMP	CAT00D7ECSSH000485
HR METER	5931	HR	SHOE	910LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER			CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		C9.3	S/N	SYE27459
Oil leakage	(FAIR) · Attn			
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR) · Attn			
Oil	(FAIR) · Attn			
Exhaust Color	(FAIR) · Attn			
US EPA	(YES) · NO			
OPERATION PUMP				
Sound	(FAIR) · Attn			
Oil leakage	(FAIR) · Attn			
Power	(FAIR) · Attn			
COOLING SYSTEM				
Radiator	(FAIR) · Attn			
Oil Cooler	(FAIR) · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	(PS) · DD	DIFF. STEERING	(YES) · NO	
Transmission	(FAIR) · Attn			
Travel	(FAIR) · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · (FAIR) · DIRTY			
Operator's Seat	(FAIR) · Attn			
Glasses	(FAIR) · Attn			
AirCon	(A/C) · H/C · H only · C only · None			
BLADE & CYLINDERS				
BLADE	(FAIR) · Attn			
CYLD.(R)	(FAIR) · Attn	シリンダー1本 SINGLE CYLINDER TYPE		
CYLD.(L)	FAIR · Attn			
TILT CYLD	(FAIR) · Attn			
ANGLE CYLD	FAIR · Attn			

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
COMMENT			
プレートと刻印のシリアルが微妙に違う			
SERIAL NUMBER: NOT EQUAL AT PLATE & STAMP			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。