

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/30	MAKE	CAT	MODEL	330FL
SERIAL	CAT0330FHL CG20021		STAMP	CAT0330FHL CG20021	
HR METER	6457	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL C7.1		S/N D8T34472	
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn A LITTLE • MIDDLE • SEVERE	
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	☒ YES	NO	
MAIN PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
OPERATING SYSTEM			
Swing	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • ☒ FAIR •	DIRTY	
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C •	H/C • H only • C only • None	
BOOM / ARM / BKT			
Boom	☒ FAIR	Attn	
Boom Cylinder	☒ FAIR	Attn	
Arm	☒ FAIR	Attn	
Arm Cylinder	☒ FAIR	Attn	
ATTACHMENT	☒ FAIR	Attn	
BKT Cylinder	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • ☒ WRIST
Multi	☒ MULTI • 2 • NO
ARM-CRANE	YES • ☒ NO
BLADE	YES • ☒ NO
OFFSET	YES • ☒ NO
OFFSET Cylinder	FAIR • Attn
Piping	☒ YES • NO Breaker only • ☒ Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。