

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/21	MAKE	KOMATSU	MODEL	PC128US-10
SERIAL	44826		STAMP	KMTPC245EFA044826	
HR METER	4075	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL 4D95LE-6 S/N 712421	
Oil leakage	☒ FAIR • Attn
Blow-By	☒ FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn
Oil	☒ FAIR • Attn
Exhaust Color	☒ FAIR • Attn
US EPA	YES • ☒ NO
MAIN PUMP	
Sound	☒ FAIR • Attn
Oil leakage	☒ FAIR • Attn
Power	☒ FAIR • Attn
COOLING SYSTEM	
Radiator	☒ FAIR • Attn
Oil Cooler	☒ FAIR • Attn
OPERATING SYSTEM	
Swing	☒ FAIR • Attn
Travel	☒ FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY
Operator's Seat	☒ FAIR • Attn
Glasses	☒ FAIR • Attn
AirCon	☒ A/C • H/C • H only • C only • None
BOOM / ARM / BKT	
Boom	☒ FAIR • Attn
Boom Cylinder	☒ FAIR • Attn
Arm	☒ FAIR • Attn
Arm Cylinder	☒ FAIR • Attn
ATTACHMENT	☒ FAIR • Attn
BKT Cylinder	☒ FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • ☒ WRIST
Multi	☒ MULTI • 2 • NO
ARM-CRANE	YES • ☒ NO
BLADE	YES • ☒ NO
OFFSET	YES • ☒ NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • ☒ NO Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。