INSPECTION SHEET 検品書 CRAWLER CRANE クローラクレーン

INSPECTION DATE		2025/10/21 MAKE		E	KOBELCO		MODEL	MODEL 7070G			
SERIAL No.	PLATE :	PLATE: GG06-05074				STAMP			GG06-05074		
HR METER	82	.94 HR	SHOE		8	00FLAT		YEAR		YR	
ENGINE: MODEL S/N					1	INTERIOR See Photos. 写真参照					
Oil leakage FAIR ・(Attn E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING					;	INTERIOR COND. CLEAN - FAIR - DIRTY					
Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE					1	Operator's Seat FAIR Attn 破れあり HUGE CUT					
Sound	FAIR · Attn					Glasses	FAIR).	Attn			
Oil	FAIR · Attn					AirCon	A/C)• H/C	· H only · C only ·	None	
Exhaust Color FAIR · Attn						UNDERCARRIAGE: See Photos. 写真参照					
OPERATION PUMP						RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4					
Sound	FAIR · Attn					COMMENT					
Oil leakage	FAIR · Attn										
Power	FAIR · Attn										
COOLING SYSTEM						WEIGHT 7					
Radiator	FAIR · Attn					ноок		70t, 32t, B	ALL		
Oil Cooler	FAIR · Attn					FREE FAI	L	YES · NO			
OPERATING SYSTEM						LIFTER YES · NO					
Computer OK)· NG						COMMENT					
Swing FAIR · Attn						@NARITA YARD					
Travel	Travel FAIR · Attn					BOOM: TOP BOTTOM, 6m × 1					
воом						70t HOOK					
MAIN B	ООМ	ТОР ВОТТОМ,	9m × 1, 6m ×	3, 3m × 1							
BOOM TOTAL		39m				@SAKURA YARD					
						BOOM: 9m×1, 6m×2, 3m×1					
TOP SHEAVE YES NO						HOOK: 32t, BALL					
JIB											
TOW	ER										
						· —					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)