

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/27	MAKE	KATO	MODEL	KRM-13H
SERIAL No.	PLATE : 5910211		STAMP : KR130-0211		
HR METER	12054	HR	Odometer	100478	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR (Attn)	*1
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR (Attn)	白煙あり WHITE FUMES

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	

OPERATING SYSTEM

Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	

TRANSMISSION

Transmission	FAIR · Attn	
No. OF GEARS	4	GEARS
4WD	4WD · 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
FREE FALL	YES	▪ NO	
HOOK	13t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		4
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

右Fサスシリンダー油漏れあり
FRONT RIGHT SUSPENSION CYLINDER: OIL LEAKING

OUTRIGGERS

OUTRIGGERS	X	•	H			
OUTRIGGERS COND.	FAIR	•	Attn			
Oil leakage (JACK CYL.)	FRONT	L	•	R	REAR	L • R
Oil leakage (SLIDE CYL.)	FRONT	L	•	R	REAR	L • R

COMMENT

*1 E/Gヘッド油漏れあり CYLINDER HEAD: OIL LEAKING 		4
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。