

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/11/11	MAKE	KUBOTA	MODEL	K-008
SERIAL	NO PLATE		STAMP	10233	
HR METER	3170	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	180R	

ENGINE : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn		
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
ATTACHMENT	FAIR · Attn		
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	
COMMENT			
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()		
Lever	LONG · WRIST		
Multi	MULTI · 2 · NO		
ARM-CRANE	YES · NO		
BLADE	YES · NO		
OFFSET	YES · NO		
OFFSET Cylinder	FAIR · Attn		
Piping	YES · NO	Breaker only · Multi	
COMMENT			
スイングシリンダー油漏れ小 SWING CYLINDER: OIL LEAKING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。