

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/11/12	MAKE	KOBELCO	MODEL	SK013
SERIAL	PN01116		STAMP	PN01116	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	230R	

ENGINE : MODEL		3TN66L	S/N	55963	
Oil leakage	FAIR	Attn	油漏れ大 SEVERE OIL LEAKING		
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE *1		
Sound	FAIR	Attn	*1		
Oil	FAIR	Attn	*1		
Exhaust Color	FAIR	Attn	*1		
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn	*1		
Oil leakage	FAIR	Attn	*1		
Power	FAIR	Attn	*1		
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	*1		
Travel	FAIR	Attn	*1		
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	破れあり CUTS		
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn	ガタあり LOOSE		
Boom Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING		
Arm	FAIR	Attn	ガタあり LOOSE		
Arm Cylinder	FAIR	Attn	*1		
ATTACHMENT	FAIR	Attn	穴あり HOLE		
BKT Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING		

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD	SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG	WRIST
Multi	MULTI	2 NO
ARM-CRANE	YES	NO
BLADE	YES	NO
OFFSET	YES	NO
OFFSET Cylinder	FAIR	Attn
Piping	YES	NO Breaker only Multi
COMMENT		
ブームとマウントのジョイント部分がおかしい、下はピンが入っていないさそう		
SWING JOINT PART: PUTTING A PLATE BETWEEN BRACKETS,		
LOWER PIN: REPLACED TO A FLAT PIPE?		
*1 E/G掛けると油漏れ大のため動作確認不可		
*1 UNABLE TO CHECK		
(ENGINE: SEVERE OIL LEAKING DURING ENGINE RUNNING)		
CNPなし WITHOUT CNP		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。