

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/28	MAKE	TADANO	MODEL	TR-250M-6
SERIAL No.	PLATE : FB2195		STAMP : TR255-0723		
HR METER	8369	HR	Odometer	54071	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Blow-By	FAIR · Attn	
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR - Attn	
Oil Cooler	FAIR - Attn	

OPERATING SYSTEM		
Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn 配管サビが多い PIPES OF BOTTOM: MUCH RUSTY

TRANSMISSION		
Transmission	FAIR • Attn	
No. OF GEARS	4 GEARS	
4WD	4WD • 6WD	

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

COMMENT

BOOM		
No. of Section	4	SECTIONS
CRACK/ENFORCEMENT	☐ FAIR ▪ Attn	
DERRICKING CYL.	☐ FAIR ▪ Attn	
EXTENSION CYL.	☐ FAIR ▪ Attn	
JIB	☐ YES ▪ NO	
JIB TYPE	STD ▪ ☐ PWR	
MAIN & SUB WIRE	☐ YES ▪ NO	
FREE FALL	☐ YES ▪ NO	
HOOK	25t, 12t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	1
TIRE WEAR (FAIR • WORN • UNEVEN WEAR)	

COMMENT	

OUTRIGGERS				
OUTRIGGERS	(X) ▪ H			
OUTRIGGERS COND.	(FAIR) ▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R

COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。