

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/23	MAKE	TADANO	MODEL	TR-250M-5
SERIAL No.	PLATE : FB0586			STAMP : TR253-2190	
HR METER	442	HR	Odometer	102755	km
TIRE SIZE	445/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	☐ FAIR · Attn	
Blow-By	☐ FAIR · ☐ Attn	A LITTLE · MIDDLE · ☒ SEVERE
Sound	☐ FAIR · Attn	
Oil	☐ FAIR · Attn	
Exhaust Color	☐ FAIR · Attn	
OPERATION PUMP		
Sound	☐ FAIR · Attn	
Oil leakage	☐ FAIR · ☐ Attn	*1
Power	☐ FAIR · Attn	
COOLING SYSTEM		
Radiator	☐ FAIR · Attn	
Oil Cooler	☐ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☐ FAIR · Attn	
Travel	☐ FAIR · Attn	
TRANSMISSION		
Transmission	☐ FAIR · ☐ Attn	*2
No. OF GEARS	3 GEARS	
4WD	☒ 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☐ FAIR · Attn	後席、切れあり W/BACK SEAT, CUTS
Glasses	☐ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section	4	SECTIONS			
CRACK/ENFORCEMENT	☐ FAIR · Attn				
DERRICKING CYL.	☐ FAIR · ☐ Attn	にじみあり OIL OOZING			
EXTENSION CYL.	☐ FAIR · Attn				
JIB	☒ YES · NO				
JIB TYPE	STD · ☐ PWR				
MAIN & SUB WIRE	☒ YES · NO				
FREE FALL	☒ YES · NO				
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					2
TIRE WEAR	FAIR · WORN · ☒ UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	☒ X · H				
OUTRIGGERS COND.	☐ FAIR · Attn				
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R	
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R	
COMMENT					
*1 油圧ポンプ下油漏れあり BOTTOM OF PUMP: OIL LEAKING					
*2 トルコン下油漏れあり					
*2 BOTTOM OF TORQUE CONVERTER: OIL LEAKING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。