

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/27	MAKE	KATO	MODEL	KR-25H-V8
SERIAL No.	PLATE : 6710386		STAMP : KRC011-0386		
HR METER	17157	HR	Odometer	100776	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) • Attn	
Blow-By	(FAIR) • Attn	A LITTLE • MIDDLE • SEVERE
Sound	(FAIR) • Attn	
Oil	(FAIR) • Attn	
Exhaust Color	(FAIR) • Attn	
OPERATION PUMP		
Sound	(FAIR) • Attn	
Oil leakage	(FAIR) • Attn	
Power	(FAIR) • Attn	
COOLING SYSTEM		
Radiator	(FAIR) • Attn	
Oil Cooler	(FAIR) • Attn	
OPERATING SYSTEM		
Computer	(OK) • NG	
Swing	(FAIR) • Attn	
Travel	(FAIR) • Attn	
TRANSMISSION		
Transmission	(FAIR) • Attn	
No. OF GEARS	4	GEARS
4WD	(4WD) • 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • (FAIR) • DIRTY	
Operator's Seat	(FAIR) • Attn	
Glasses	(FAIR) • Attn	
AirCon	(A/C) • H/C • H only • C only • None	
COMMENT		

BOOM					
No. of Section	4		SECTIONS		
CRACK/ENFORCEMENT	(FAIR)	▪ Attn			
DERRICKING CYL.	(FAIR)	▪ Attn			
EXTENSION CYL.	(FAIR)	▪ Attn			
JIB	(YES)	▪ NO			
JIB TYPE	STD	▪ (PWR)			
MAIN & SUB WIRE	(YES)	▪ NO			
FREE FALL	YES	▪ (NO)			
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					1
TIRE WEAR	FAIR (WORN) UNEVEN WEAR				
COMMENT 穴あり MUCH HUGE HOLES					
OUTRIGGERS					
OUTRIGGERS	X	▪ (H)			
OUTRIGGERS COND.	(FAIR)	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					
					1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。