

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/29	MAKE	KOMATSU	MODEL	PC120-8
SERIAL	83394		STAMP	KMTPC202C01083394	
HR METER	11081	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		4D95LE-5	S/N	518196
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn	油漏れあり OIL LEAKING	
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり TORN	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
None				
BOOM / ARM / BKT				
Boom	FAIR	Attn	溶接クラックあり WELDED PART: CRACKED	
Boom Cylinder	FAIR	Attn	左右油漏れあり CYLINDERS: OIL LEAKING	
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn	にじみあり OIL OOZING	
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	にじみあり OIL OOZING	

UNDERCARRIAGE : See Photos. 写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)3

COMMENT
左右走行モーターにじみあり TRAVEL MOTORS: OIL OOZING

BKTSTD / SLOPE / NARROW / SKELETON / OTHER()

LeverLONG • WRIST

MultiMULTI • 2 • NO

ARM-CRANEYES • NO

BLADEYES • NO

OFFSETYES • NO

OFFSET CylinderFAIR • Attn

PipingYES • NOBreaker only • Multi *1

COMMENT
A/C風出ない A/C: NOT BLOWING AIR
*1 右メクラにじみあり RIGHT CAP: OIL OOZING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。