

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/23	MAKE	KOBELCO	MODEL	SK135SR-1E
SERIAL	YY03-04961			STAMP	YY03-04961
HR METER	13143	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL		4BG1	S/N	191226
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	左側にじみあり LEFT CYLINDER: OIL OOZING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn	油漏れあり OIL LEAKING	
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON (OTHER))
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
アタッチメント: フォーク付マグネット ATTACHMENT: MAGNET-FORK	
MAKE: KOBELCO YS-900HAG-NP-1426	
コントロールバルブ油漏れ小 CONTROL VALVE: OIL LEAKING	
P2ポンプ比例弁関連警告あり	
WARNING DISPLAY FOR P2 PUMP PROPORTIONAL VALVE	
ハイCAB仕様 HIGH CAB	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。