

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/22	MAKE	KATO	MODEL	KRM-25H
SERIAL No.	PLATE : 0613028		STAMP : KR248-3028		
HR METER	17143	HR	Odometer	149657	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR (Attn)	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	

OPERATION PUMP

Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM

Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR • Attn
No. OF GEARS	4
4WD	4WD • 6WD

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	•	FAIR	•	DIRTY
----------------	-------	---	------	---	-------

Operator's Seat	FAIR • Attn
Glasses	FAIR • Attn

AirCon	A/C	H/C	H only	C only	None
--------	------------	-----	--------	--------	------

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
FREE FALL	YES	▪ NO	
HOOK	25t,	BALL	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	3
---	----------

TIRE WEAR	FAIR • WORN • UNEVEN WEAR
-----------	---------------------------

COMMENT

右Fウインカーレンズ破損あり FRONT RIGHT BLINKER COVER: BROKEN

OUTRIGGERS

OUTRIGGERS	X	•	(H)	*1
OUTRIGGERS COND.	(FAIR)	•	Attn	
Oil leakage (JACK CYL.)	FRONT	L	• R	REAR L (R)
Oil leakage (SLIDE CYL.)	FRONT	L	• R	REAR L • R

COMMENT

*1 左Fストロークセンサー不良

*1 FRONT LEFT OUTRIGGER EXTENSION SENSOR: MALFUNCTION

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。