

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/22	MAKE	KOMATSU	MODEL	PC138US-11
SERIAL	57398			STAMP	KMTPC261LLA057398
HR METER	11904	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	白煙あり WHITE FUMES
US EPA	YES • NO	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	ガタあり SWING: LOOSE
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • Attn	
Arm	FAIR • Attn	ガタあり LOOSE
Arm Cylinder	FAIR • Attn	
ATTACHMENT	FAIR • Attn	
BKT Cylinder	FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。