

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/22	MAKE	KOMATSU	MODEL	WA320-5
SERIAL	60223	STAMP	W105-60223		
HR METER	UNKNOWN	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	20.5-25	YEAR	YR

ENGINE : MODEL 6D102E-2 S/N 26338275	
Oil leakage	FAIR • Attn
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn 白煙小 A LITTLE WHITE FUMES
US EPA	YES • NO
OPERATION PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS • DD
Transmission	FAIR • Attn
Travel	FAIR • Attn *1
FOOT BRAKE	FAIR • Attn
PARKING BRAKE	FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY
Operator's Seat	FAIR • Attn
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • None
FRONT & CYLINDERS	
Arm	FAIR • Attn
Bell crank	FAIR • Attn
Bucket	FAIR • Attn
Articulate	FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES • NO
ATTACHMENTS	
STD BKT	YES • OTHER
BLADE	YES • NO Piping for Tilt YES • NO
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
付属品: マルチプラウ MULTI PLOW AS SPARE	
*1 アクセルペダル戻り悪い ACCELERATOR PEDAL: HARD TO RETURN	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。