

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/11/26	MAKE	YANMAR	MODEL	B7-5A
SERIAL	57689			STAMP	57689B
HR METER	5868	HR	YEAR	2005	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G PADS

ENGINE : MODEL		4TNV98	S/N	11835
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn	にじみあり OIL OOZING	
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn	*1	
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	穴あり HOLE	
Glasses	FAIR	Attn	天井窓クラックあり SKYLIGHT: CRACKED	
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO *2
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
CAB下油汚れあり BOTTOM OF CAB: OIL STAINS	
A/Cベルト緩い A/C BELT: LOOSE	
*1 HI/LO切替え不良、右クローラー前進のみパワー弱い、 作動油入っているが走行中に息つぎが起こる	
*1 HI/LO SWITCH: MALFUNCTION, RIGHT TRACK: WEAK POWER WHEN JUST TRAVELING FORWARD, NOT SMOOTH TRAVELING LIKE OFTEN CATCHING ON SOMETHING (HYDRAULIC OIL LEVEL: OK)	
*2 本体上げたまま保持不可、自然降下あり	
*2 UNABLE TO KEEP PUSHING UP THE BODY BY BLADE, HYDRAULIC DRIFT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。