

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/28	MAKE	TADANO	MODEL	GR-500N-1
SERIAL No.	PLATE :	582970	STAMP :	TR552-0389	
HR METER	15876	HR	Odometer	80606	km
TIRE SIZE	505/95R25		YEAR		YR

ENGINE : MODEL		S/N
Oil leakage	(FAIR) • Attn	
Blow-By	(FAIR) • Attn	A LITTLE • MIDDLE • SEVERE
Sound	(FAIR) • Attn	
Oil	(FAIR) • Attn	
Exhaust Color	(FAIR) • Attn	
OPERATION PUMP		
Sound	(FAIR) • Attn	
Oil leakage	(FAIR) • Attn	
Power	(FAIR) • Attn	
COOLING SYSTEM		
Radiator	(FAIR) • Attn	
Oil Cooler	(FAIR) • Attn	
OPERATING SYSTEM		
Computer	(OK) • NG	
Swing	(FAIR) • Attn	
Travel	(FAIR) • Attn	
TRANSMISSION		
Transmission	(FAIR) • Attn	
No. OF GEARS	4	GEARS
4WD	(4WD) • 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • (FAIR) • DIRTY	
Operator's Seat	(FAIR) • Attn	
Glasses	(FAIR) • Attn	
AirCon	(A/C) • H/C • H only • C only • None	
COMMENT		

BOOM						
No. of Section	6		SECTIONS			
CRACK/ENFORCEMENT	FAIR	▪	Attn			
DERRICKING CYL.	FAIR	▪	Attn			
EXTENSION CYL.	FAIR	▪	Attn			
JIB	YES	▪	NO			
JIB TYPE	STD	▪	PWR			
MAIN & SUB WIRE	YES	▪	NO			
FREE FALL	YES	▪	NO			
HOOK	51t, 25t, BALL					
UNDERCARRIAGE : See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)						3
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR					
COMMENT						
OUTRIGGERS						
OUTRIGGERS	X	▪	H			
OUTRIGGERS COND.	FAIR	▪	Attn			
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L	▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L	▪ R
COMMENT						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。