

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/23	MAKE	KOMATSU	MODEL	LW80M-1
SERIAL No.	PLATE : 10047			STAMP : L002-10047	
HR METER	3627	HR	Odometer	11326	km
TIRE SIZE	11R22.5			YEAR	YR

ENGINE : MODEL S/N

Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	

TRANSMISSION

Transmission	FAIR	Attn	ミッションにじみあり OIL OOZING
No. OF GEARS	3	GEARS	
4WD	4WD	6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C H/C · H only · C only · None

COMMENT

BOOM

No. of Section	5	SECTIONS	
CRACK/ENFORCEMENT	FAIR	Attn	
DERRICKING CYL.	FAIR	Attn	
EXTENSION CYL.	FAIR	Attn	自然降下大 MUCH HYDRAULIC DRIFT
JIB	YES	NO	
JIB TYPE	STD	PWR	
MAIN & SUB WIRE	YES	NO	
FREE FALL	YES	NO	
HOOK	4.9t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	X	H	
OUTRIGGERS COND.	FAIR	Attn	
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R

COMMENT

レバースタンド中立不良	
LEVER STAND: UNABLE TO KEEP THE NEUTRAL POSITION	
*1 E/G下部にじみあり BOTTOM OF ENGINE: OIL OOZING	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。