

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/23	MAKE	KOMATSU	MODEL	PC120-8
SERIAL	84255		STAMP	KMTPC202V01084255	
HR METER	6311	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N	528282
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES · NO	文字読めない STICKER: UNREADABLE	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	ファンベルト鳴きあり FAN BELT: NOISES
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	左右油漏れ小 CYLINDERS: OIL LEAKING
Arm	FAIR	Attn	ガタあり LOOSE
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	フレームと本体部ガタあり FRAME & BOX: LOOSE
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
BKT	STD / SLOPE / NARROW / SKELETON OTHER BREAKER)				
Lever	LONG	▪	WRIST		
Multi	MULTI	▪	2 ▪ NO		
ARM-CRANE	YES	▪	NO		
BLADE	YES	▪	NO		
OFFSET	YES	▪	NO		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	YES	▪	NO	Breaker only ▪ Multi	1 *1
COMMENT					
A/Cエラー表示あり A/C ERROR DISPLAY					
*1 後付け、ペダル踏んでも油圧起きない					
*1 PIPING: RETROFITTED,					
UNABLE TO SUPPLY ANY HYDRAULIC PRESSURE					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。