

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/30	MAKE	HITACHI	MODEL	EX120-3
SERIAL	12V-41174		STAMP	12V-41174	
HR METER	5657	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	右側にじみあり RIGHT CYLINDER: OIL OOZING
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	にじみあり OIL OOZING

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。