

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2025/10/21	MAKE	KOBELCO	MODEL	SK100W-2
SERIAL	YE03-02437		STAMP	YE02-2437	
HR METER	7071	HR	Odometer	6912	km
				YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS		CNP / CNP / NONE	TIRE SIZE	9.00-20

ENGINE : MODEL		6D34	S/N	097187
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · (NO)			

MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C H/C H only C only None		

BOOM / ARM / BKT		
Boom	FAIR ・ Attn	
Boom Cylinder	FAIR ・ Attn	右側にじみあり RIGHT CYLINDER: OIL OOZING
Arm	FAIR ・ Attn	
Arm Cylinder	FAIR ・ Attn	
ATTACHMENT	FAIR ・ Attn	
BKT Cylinder	FAIR ・ Attn	油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR (FAIR) • WORN • UNEVEN WEAR	

COMMENT
左Fタイヤ周り油漏れあり(ブーツ切れあり)
AROUND FRONT LEFT TIRE: OIL LEAKING (BOOT: CUT)

BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG • (WRIST)
Multi	(MULTI) • 2 • NO

ARM-CRANE	YES	☒ NO
-----------	-----	-------------------------------------

BLADE	YES • NO	
-------	-----------------	--


OFFSET	YES	☒ NO
--------	-----	-------------------------------------

OFFSET Cylinder	FAIR ▪ Attn
-----------------	-------------

Piping	YES ▪ NO	Breaker only ▪ Multi
--------	-----------------	-----------------------------

OUTRIGGERS COND.	FAIR	▪ Attn
------------------	------	--------

COMMENT
プレートとスタンプが違う
SERIAL NUMBER: NOT EQUAL AT PLATE & STAMP

		3
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。