

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/20	MAKE	KOMATSU	MODEL	PC60-6
SERIAL	29796		STAMP	PC60-29796	
HR METER	11273		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450R	

ENGINE :		MODEL	4D95L-1	S/N	67608
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn	白煙あり WHITE FUMES		
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	ゴリゴリ感、ガタあり RATTLING, SWING: LOOSE		
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
ATTACHMENT	FAIR	Attn	ガタあり LOOSE		
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT 右走行モーター油漏れ小、左油漏れあり TRAVEL MOTORS: OIL LEAKING	
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	(LONG) ・ WRIST
Multi	MULTI ・ 2 ・ (NO)
ARM-CRANE	YES ・ (NO)
BLADE	YES ・ (NO)
OFFSET	YES ・ (NO)
OFFSET Cylinder	FAIR ・ Attn
Piping	YES ・ (NO) Breaker only ・ Multi
COMMENT E/Gフードヒンジ破損あり ENGINE HOOD HINGES: BROKEN ブーム下ホースひび割れあり SOME HOSES AROUND LOWER PART OF BOOM: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。