

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/10/20	MAKE	KOMATSU	MODEL	D20A-8
SERIAL	83128		STAMP	KMT0D057V01083128	
HR METER	2951	HR	SHOE	300G	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · (DD)	DIFF. STEERING YES · (NO)
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
BLADE & CYLINDERS		
BLADE	(FAIR) · Attn	
CYLD.(R)	(FAIR) · Attn	
CYLD.(L)	(FAIR) · Attn	
TILT CYLD	(FAIR) · Attn	
ANGLE CYLD	(FAIR) · Attn	

UNDERCARRIAGE See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT 		
Ripper	MULTI · S/S	Shanks PCS
Ripper CYLD.	FAIR · Attn	
COMMENT 		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。