

INSPECTION SHEET 検品書
TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2025/10/28	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE		
MAKE	SUMITOMO		MODEL	HC-118RM	
SERIAL	HC118-0029		STAMP	HC118-0029	
HR METER	CRANE: 985 / CHASSIS: 5169	HR	Odometer	9541 km	YEAR 1988 YR
CHASSIS	MODEL P-KG54V	No.	00011	TIRE	13.00-20

ENGINE(CRANE) : MODEL		S/N 550217
Oil leakage	FAIR ☒ Attn	オイルパン油漏れあり OIL PAN: OIL LEAKING
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
ENGINE(CHASSIS) : MODEL		S/N
Oil leakage	FAIR ☒ Attn	
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	*1
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Computer	OK ☐ NG ☐	
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	AT ☒ MT ☐	No. OF GEARS 7 GEARS
Transmission	FAIR ☒ Attn	
No. of DRIVE WHEELS	2 WD	
Travel	FAIR ☒ Attn	
FOOT BRAKE	FAIR ☒ Attn	
PARKING BRAKE	FAIR ☒ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ FAIR ☐ DIRTY ☒	
Operator's Seat	FAIR ☒ Attn	
Glasses	FAIR ☒ Attn	
AirCon	A/C ☐ H/C ☐ H only ☐ C only ☒ NONE ☐	

CRANE	
WEIGHT	1
HOOK	50t
BOOM	
MAIN BOOM	TOP, BOTTOM, 6m × 1, 3m × 2
BOOM TOTAL	24m
No. of Section	- SECTIONS
TOP SHEAVE	YES ☒ NO ☐
JIB	STD ☐ PWR ☐
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	FAIR ☒ WORN ☐ UNEVEN WEAR ☐
COMMENT	
シャシーE/Gカバーなし ENGINE HOOD OF CHASSIS: MISSING	
*1 サビあり、水少ない RUSTY, COOLANT: NOT ENOUGH	
@NARITA YARD	
BOOM: TOP, BOTTOM	
50t HOOK	
@SAKURA YARD	
BOOM: 6m × 1, 3m × 2	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。