

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/23	MAKE	KATO	MODEL	KR-25H-V5
SERIAL No.	PLATE : 5413143		STAMP : KR258-3143		
HR METER	34072 HR		Odometer	72256 km	
TIRE SIZE	385/95R25		YEAR	2007 YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR • Attn	
No. OF GEARS	4	GEARS
4WD	4WD • 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	

COMMENT

[illegible]

BOOM

No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn
DERRICKING CYL.	FAIR	▪ Attn
EXTENSION CYL.	FAIR	▪ Attn
JIB	YES	▪ NO
JIB TYPE	STD	▪ PWR
MAIN & SUB WIRE	YES	▪ NO
FREE FALL	YES	▪ NO
HOOK	25t, BALL	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		1
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

OUTRIGGERS

OUTRIGGERS	X	▪	H						
OUTRIGGERS COND.	FAIR	▪	Attn						
Oil leakage (JACK CYL.)	FRONT		L	▪	R	REAR	L	▪	R
Oil leakage (SLIDE CYL.)	FRONT		L	▪	R	REAR	L	▪	R

COMMENT

[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。